

3. River Level Status of Gauging Station

Sl Nos.	Station Type	River Basin Number	Basin Name	Name of River	Station Name	Highest Water Level Recorded (m)	Water Level (m) recorded at 9 AM Yesterday	Water Level(m) recorded at 9 AM Today	Water Level Rise (+)/Fall (-) in meters during last 24 Hrs ending at 9 AM Today	Weather Condition	Downstream Settlement		
1	AWLS	Basin I	Wang Chhu	Thin Chhu	Dodena		1.94	1.94	0.00	Cloudy	Thimphu Valley and Downstream		
2	Principal				Lungtenphu	2.82	1.32	1.33	0.01	Cloudy			
3	Principal				Damchu	6.00	2.90	2.91	0.01	Cloudy			
4	Secondary			Haa Chhu	Haa	2.60	1.03	1.00	-0.03	Cloudy	Haa and Wang Chhu Downstream		
5	Principal			Pa Chhu	Bondlay		1.47	1.47	0.00	Cloudy	Downstream of Paro Valley and Wang Chhu Basin		
6	Principal			Amo Chhu	Dorokha		3.30	3.35	0.05	Cloudy	Sanise, Phunsholing and Downstream		
7	Secondary				Droyagang		7.07	3.46	3.55	0.09	Light Rain	Phunsholing and Downstream	
8	Secondary				Samdingkha		6.10	3.95	3.93	-0.02	Partly Sunny	Puna-Wangdue Valley and Downstream	
9	Principal	Basin II	Punatsang Chhu	Mo Chhu	Yebesa		3.94	2.32	2.27	-0.05	Rainy	Mo Chhu Valley and Downstream	
10	Secondary								3.05	3.20	0.15	Cloudy	
11	Principal					Wangdue Rapid		7.82	3.47	3.52	0.05	Partly Cloudy	PHPA I,PHPA II and Downstream
12	Principal			Punatsang Chhu	Turitar Sunkosh		6.68	3.40	3.50	0.10	Cloudy	Downstream of Dagana and Lhamoizingkha	
13	Secondary				Sunkosh Bridge		2.65	2.85	0.20	Cloudy			
14	Principal				Kerabari		11.90	5.68	5.85	0.17	Cloudy		
15	Secondary				Mao Chhu	Sherzhong		4.00	4.00	0.00	Rainy	Gelephu Valley and Downstream	
16	Principal			Basin III	Manas	Mangdue Chhu	Bijzam		5.35	2.70	2.76	0.06	Partly Cloudy
17	Secondary	Dakpai Chhu					2.26	1.59	1.61	0.02	Cloudy	Downstream of Zhemgang and Panbang	
18	Principal	Tingtibi					7.45	3.93	4.14	0.21	Cloudy		
19	Principal	Chamkhar Chhu	Kurjey				4.00	2.40	2.44	0.04	Cloudy	Chamkhar Valley, Zhemgang and Downstream	
20	Principal		Shingkar (Bemshang)					2.35	2.34	-0.01	Light Rain	Zhemgang and Downstream	
21	Principal	Kuri Chhu	Sumpa				7.65	5.05	4.90	-0.15	Cloudy	Lhuntse Downstream,Kurizampa,KHPA and Downstream along the Kuri Chhu	
22	Secondary		Khoma				5.30	2.38	2.35	-0.03	Cloudy		
23	Secondary		Autsho				8.48	4.95	4.95	0.00	Cloudy		
24	Principal		Kurizampa				18.45	9.11	9.40	0.29	Rainy		
25	Principal	Kholong Chhu	Muktirap				6.00	2.95	2.95	0.00	Cloudy	Doksum,Kholong Chhu Hydro Power Project and Downstream of Gongri Chhu	
26	Secondary							4.35	4.37	0.02	Cloudy	Kholong Chhu Hydro Power Project and Downstream of Gongri Chhu	
27	Secondary	Drangme Chhu	Chazam					9.45	9.50	0.05	Rainy	Downstream Settlement of Kuri-Gongri and Panbang	
28	Principal		Omzong		6.75	2.94	2.87	-0.07	Light Rain				
29	Secondary		Sheri Chhu		2.58	1.65	1.68	0.03					
30	Principal		Panhang		12.48	6.34	6.45	0.11	Rainy				
31	Principal	Ngara Ama Chhu	Pangzam			6.10	6.00	-0.10	Cloudy	Bangtar Settlement and Downstream			
32	Principal		Bangtar			2.25	2.28	0.03	Cloudy	Downstream of Bangtar Settlement			

NOTE The Water Level are relative Gauge Hight of the Observation site reference to the Site Specific and doesnot represent the actual water depth.

ALERT

MISSING

NR Represent that the Data has not been reported or Not Updated
GLOF & Rainstorm Early Warning System of Mangdue Chhu and Chamkhar Chhu Sub Basin is down.

ISSUED BY: FMCR,HWRSD,NCHM