



3. River Level Status of Gauging Station

Sl Nos.	Station Type	River Basin Number	Basin Name	Name of River	Station Name	Highest Water Level Recorded (m)	Water Level (m) recorded at 9 AM Yesterday	Water Level(m) recorded at 9 AM Today	Water Level Rise (+)/Fall (-) in meters during last 24 Hrs ending at 9 AM Today	Weather Condition	Downstream Settlement		
1	AWLS	Basin I	Wang Chhu	Thin Chhu	Dodena		NR	1.96	#VALUE!	partly sunny	Thimphu Valley and Downstream		
2	Principal				Lungtenphu	2.82	1.36	1.32	-0.04	partly sunny			
3	Principal					Damchu	6.00	2.90	2.86	-0.04	Sunny	Chukha and Downstream	
4	Secondary					Haa Chhu	Haa	2.60	1.13	1.09	-0.04	Sunny	Haa and Wang Chhu Downstream
5	Principal					Pa Chhu	Bondlay		1.42	1.39	-0.03	Cloudy	Downstream of Paro Valley and Wang Chhu Basin
6	Principal					Amo Chhu	Dorokha		3.35	3.35	0.00	Cloudy	Sanise, Phunsholing and Downstream
7	Secondary						Droyagang	7.07	3.40	3.33	-0.07	Cloudy	Phunsholing and Downstream
8	Secondary					Pho Chhu	Samdingkha	6.10	3.68	3.68	0.00	Sunny	Puna-Wangdue Valley and Downstream
9	Principal	Basin II	Punatshang Chhu	Mo Chhu	Yebesa	3.94	2.00	2.09	0.09	Sunny	Mo Chhu Valley and Downstream		
10	Secondary						Wangdue Bridge		2.45	2.60	0.15	Sunny	PHPA I,PHPA II and Downstream
11	Principal					Wangdue Rapid	7.82	2.87	3.08	0.21	Sunny		
12	Principal					Punatshang Chhu	Turitar Sunkosh	6.68	3.15	3.45	0.30	partly cloudy	Downstream of Dagana and Lhamoizingkha
13	Secondary						Sunkosh Bridge		2.35	2.60	0.25	Cloudy	
14	Principal						Kerabari	11.90	5.42	5.57	0.15	Sunny	
15	Secondary					Mao Chhu	Sherzhong		3.90	4.00	0.10	Sunny	Gelephu Valley and Downstream
16	Principal			Basin III	Manas	Mangdue Chhu	Bijam	5.35	2.51	2.51	0.00	Sunny	MHPA Dam,Power House and Downstream of Trongsa & Zhemgang
17	Secondary						Dakpai Chhu	2.26	0.63	0.61	-0.02	partly cloudy	Downstream of Zhemgang and Panbang
18	Principal						Tingtibi	7.45	3.95	3.92	-0.03		
19	Principal					Chamkhar Chhu	Kurjey	4.00	2.25	2.22	-0.03	Sunny	Chamkhar Valley, Zhemgang and Downstream
20	Principal						Shingkar (Benshang)		2.06	2.02	-0.04	Sunny	Zhemgang and Downstream
21	Principal					Kuri Chhu	Sumpa	7.65	4.20	4.24	0.04	Cloudy	Lhuntse Downstream,Kurizampa,KHPA and Downstream along the Kuri Chhu
22	Secondary						Khoma	5.30	1.93	1.98	0.05		
23	Secondary						Autsho	8.48	4.21	4.21	0.00	cloudy with sunny	
24	Principal						Kurizampa	18.45	8.40	8.44	0.04	Cloudy	
25	Principal					Kholong Chhu	Muktrirap	6.00	2.37	2.43	0.06	Cloudy	Doksam,Kholong Chhu Hydro Power Project and Downstream of Gongri Chhu
26	Secondary						Doksum		4.27	4.22	-0.05	Sunny	Kholong Chhu Hydro Power Project and Downstream of Gongri Chhu
27	Secondary					Drangme Chhu	Chazam		8.55	8.65	0.10	Sunny	Downstream Settlement of Kuri-Gongri and Panbang
28	Principal						Omzong	6.75	2.30	2.32	0.02	Sunny	
29	Secondary						Sheri Chhu	2.58	1.65	1.64	-0.01		
30	Principal			Panhang	12.48		5.91	6.01	0.10	Sunny	Manas and Downstream		
31	Principal			Ngara Ama Chhu	Pangzam		6.45	6.05	-0.40	Sunny	Bangtar Settlement and Downstream		
32	Principal				Bangtar		2.27	2.32	0.05	Sunny	Downstream of Bangtar Settlement		

NOTE The Water Level are relative Gauge Hight of the Observation site reference to the Site Specific and doesnot represent the actual water depth.

ALERT

WARNING

NR Represent that the Data has not been reported or Not Updated

ISSUED BY: FMCR,HWRSD,NCHM